

INFORMAL SOLICITATION: Softball Bullpen Updates
Opened 11/14/2024

AWARDED


STEPHEN F. AUSTIN
STATE UNIVERSITY
NACOGDOCHES, TEXAS

HUB Status			
Bidder	DTurfMeister	Sports Field Solutions	Fields in Grass
Address	201 Coventry St. Bullard, TX 75757	5146 Gebron Dr Benbrook, TX 76126	P.O. Box 754 Mansfield, TX 76063
Phone / Fax			

Item	Description	Qty	Unit	Unit Price	Extens	Unit Price	Extens	Unit Price	Extens
							-		-
	Home Bullpen Renovation, Remove existing ties and grass. Add concrete base to home plate turf area and install 1,150 sf of used turf. Add select material to 1,150 sf pitching area, install (3) new pitching rubbers, install mound clay blocks in pitching lanes and add conditioner.	1	ea	13,437.00	13,437.00		-		-
							-		-
	Visitor Bullpen Renovation, Remove top row of existing ties. Add concrete base to home plate turf area and install 900 sf of used turf. Add select material to 500 sf pitching area, install (2) new pitching rubbers, install mound clay blocks in pitching lanes and add conditioner.	1	ea	9,446.00	9,446.00		-		-
							-		-
	Provide and Install Backstop Frame and Net behind home plate areas of each home plate area.	1	ea	4,980.00	4,980.00		-		-
					-		-		-
	Turnkey price for Bullpen renovations	1			-	34,000.00	34,000.00		35,860.00
					-				
			ea		-				
			ea		-				
			ea		-				
			ea		-				
			ea		-				
TOTAL					\$ 27,863.00		\$ 34,000.00		\$ 35,860.00

TERMS	
F.O.B.	
DELIVERY	

I certify that the above included all firms that have been contacted for bids, and their replies are exactly as stated.
Reason for award to other than low bidder/Other documentation:


Signature